Rostock MAX Assembly Instructions
Step 6 - Final Frame Assembly
SeeMeCNC.com
November, 15 2012