Rostock MAX Assembly Instructions
Step 1.2 - Stepper & Idler Bearing Assembly
SeeMeCNC.com
November, 8 2012